

PL-1550 Circuit Subassemblies



GOODYEAR
ELECTRONICS, INC.

NSN	Part Number	Nomenclature	New PN	Repair Price
5998-01-574-7305	7010-6630-000	UUT Interface Card		\$3,500.00
5998-01-574-7086	7010-6630-100	Front Panel Switch Matrix Card		\$3,000.00
N/A	7010-6630-200	Front Panel BNC Connector Card		\$500.00
5998-01-574-8229	7010-6630-300	CPU Card		\$4,500.00
5998-01-574-8656	7010-6630-400	RF Card		\$3,500.00